	Friends of the Bay 2020 Water Quality Data - Site 1, Cold Spring Cove South																																				
	Date	Time	H20 Temp TOP (0.5m)	H20 Temp 1.0 m	H20 Temp 0.5 m from BTM	Salinity TOP	Salinity 1.0	Salinity BTM	PH Top	PH 1.0	Ph .5 m from BTM	Top DO	DO 1.0	BTM DO	Secchi	Floor Depth (meters)	Air Temp (°C)	H2O Temp BTM monthly AVG	Fecal Coliform Bacteria	Enterococci	Ammonia (NH3)	Nitrate NO3	Nitrite (NO2)	Total Kjeldahl Nitrog	Organic Nitrogen (N)	Total Nitrogen	Rainfall in	Tidal Stage	Water Color	Surface Conv	Cloud Cov	Wind DIR	Wind SPE	Weather	Wave Height		Data Entered by	Captain	Sampling Leader
Site 1	7/13/2020	12:12pm	MANTA AMPHIBIAN HANDHELD AND SENSOR NOT WORKING - WATER SAMPLE COLLECTED FOR DEPT OF HEALTH												1.1m		29.1		107	<1							1	2	5	6	3	2	1	2	0		kp	pj	pj
Site 1	7/20/2020	11:19AM	25.90	24.79	23.48	24.03	24.38	25.46	8.07	7.92	7.42	6.06	4.68	3.51	0.9m	5.87	34.1		65	<1							0	4	5	6	1	1	1	2	0		LD	PJ	pj
Site 1	7/27/2020	11:54AM	26.33	26.38	24.22	24.31	24.35	25.71	8.04	8.03	7.23	7.23	5.05	2.68	0.8m	3.64	32.4	ACKED DUE TO EXTREME HEAT 100+ DEGREES								0	3	1	6	1	8	1	2	0		LD	PJ	PJ
Site 1	8/3/2020	10:33AM	24.41	24.25	23.09	24.81	25.03	25.97	7.63	7.62	7.37	4.91	3.92	3.20	1.3m	5.85	32.0		46	2							0	4	5	6	0	7	1	1	0		LD	PJ	PJ
Site 1	8/10/2020	11:37AM	25.32	23.85	23.42	24.89	25.81	26.50	7.73	7.26	7.12	3.50	2.91	3.59	1.2m	4.15	28.4		15	<1							0	4	5	4	1	1	1	2	0		LD	PJ	PJ
Site 1	8/17/2020	10:21am	22.82	23.19	23.34	22.52	24.87	26.09	7.51	7.43	7.33	3.59	3.03	3.31	1.2	5.9	22.7		180	11							2	1	5	6	1	8	1	1	1		kp	pj	pj
Site 1	8/24/2020	11:52am	25.07	24.58	24.20	24.76	26.12	26.70	7.47	7.49	7.23	4.41	3.90	3.40	1.1	3.89	31.9		27	1							0	4	5	ools)	1	8	1	2	1		kp	pj	pj
Site 1	8/31/2020	10:46am	23.44	24.32	24.47	24.21	25.37	26.53	ing used backup	t have pH sensor	NA	6.14	5.95	6.18	1.0M	5.99	23.2		30	12							1	4	5	6	4	0	0	3	0		kp	pj	pj
Site 1	9/8/2020	11:21am	24.14	24.00	24.01	25.90	26.24	26.99	ing used backup	t have pH sensor		4.08	3.75	3.91	1.1m	4.53	27.2		3	<1							0	4	5	d fish	2	1	1	2	1		kp	pj	pj
Site 1	9/14/2020	9:32am	onitoring Equip. Malfunction,	ilinity, pH and DO	sent in for repair	ality Monitoring Equip. Malfunction,		ilinity, pH and DO	sent in for repair	Water Quality Monitoring Equip. Malfunction, ilinity, pH and DO				sent in for repair			22.6		34	7							0	1	5	6	4	8	2	3	2		kp	pj	pj
Site 1	9/21/2020	10:30am	17.52	17.51	19.26	24.89	24.86	26.26				7.55	7.02	6.82	0.9M	3.69	16.0		290	3							0	4	5	6	0	2	2	1	1		kp	pj	pj
Site 1	9/28/2020		short on time	short on time	short on time																																
Site 1	10/5/2020	9:50 am	18.34	18.36	19.73	24.79	24.85	26.49		broken		7.34	7.13	7.29	1.1	4.30	16.1		86	6							0	4	5	6	4	3	1	3	1		PJ	PJ	PJ
Site 1																																					
Site 1																																					
Site 1																																					
Site 1																																					
Site 1																																					
Site 1																																					
Site 1																																					
Site 1																																					
Site 1																																					
Site 1																																					
Site 1																																					
Site 1																																					
Site 1																																					
Site 1																																					
Site 1																																					
Site 1																																					

| | Friends of the Bay 2020 Water Quality Data - **Site 2, Cold Spring Cove North** | | |

| | Friends of the Bay 2020 Water Quality Data - Site 3, Cold Spring Harbor South | | |

| | Friends of the Bay 2020 Water Quality Data - Site 4, Cold Spring Harbor North | | |

	Friends of the Bay 2020																																					
	Date	Time	H20 Temp TOP (0.5m)	H20 temp 1.0 m	H20 Temp 0.5 m from BTM	Salinity TOP	Salinity 1.0 m	Salinity BTM	PH Top	PH 1.0 m	Ph .5 m from BTM	Top DO	DO 1.0 m	BTM DO	Secchi	Floor Depth (meters)	Air Temp	H2O Temp BTM	Fecal Coliform Bacteria	Enterococci	Amm	Nitrat	Nitri te	Org a	Total	Rainfall in 24 hours	Tidal Stage	Water Color	Surface Condition	Cloud Cover	Wind DIRECTON	Wind SPEED	Weather	Wave Height		Data Entered by	Captain	Sampling Leader	Notes			
Site 5	7/13/2020	11:26am	IOT WORKING		WATER SAMPLE COLLECTED FOR DOH										1.6m		30.4		1	3	IRKING					1	2	5	6	1	2	0	1	1		kp	pj	pj				
Site 5	7/20/2020	9:33AM	24.95	24.56	23.30	25.48	25.52	25.92	7.98	7.94	7.70	6.86	6.16	4.93	1.5m	13.19	32.2		1	1						0	4	5	6	3	6	1	2	0		LD	PJ	PJ				
Site 5	7/27/2020	11:01AM	25.67	25.10	24.52	26.20	26.29	26.35	7.85	7.85	7.79	6.86	6.63	6.27	1.0m	10.17	35.0		<1	<1						0	2	5	6	1	7	1	2	0		LD	PJ	PJ				
Site 5	8/3/2020	9:44AM	23.81	23.65	22.94	26.07	26.02	26.22	7.57	7.55	7.47	4.5	4.34	3.86	1.7m	12.42	26.9		3	1						0	4	5	6	1	7	1	1	1		LD	PJ	PJ				
Site 5	8/10/2020	10:26AM	24.83	24.59	23.46	26.73	26.69	26.94	7.74	7.71	7.48	6.55	5.70	4.80	1.6m	10.11	33.3		<1	<1						0	2	5	6	0	4	1	1	0		LD	PJ	PJ				
Site 5	8/17/2020	9:30am	23.00	22.82	22.48	26.73	26.77	26.92	7.58	7.55	7.50	4.47	4.32	4.15	2.3m	11.6	21.1		2	1						2	4	5	6	1	8	2	2	1		kp	pj	pj				
Site 5	8/24/2020	10:55am	25.60	24.85	24.59	27.23	27.17	27.27	7.78	7.63	7.57	6.91	6.44	6.16	1.4m	10.54	32.7		<1	<1						0	4	5	6	1	8	1	2	1		kp	pj	pj				
Site 5	8/31/2020	9:52am	24.17	24.16	23.93	27.09	27.08	27.07	g used backup		have pH sensor	6.26	6.44	6.78	1.7m	3.00	24.5		1	8						1	4	5	6	4	2	1	3	0		kp	pj	pj				
Site 5	9/8/2020	10:22am	24.04	to take reading	24.03	27.24	to take reading	27.25	g used backup		have pH sensor	6.30	to take reading	6.58	1.0m	1.86	26.6		<1	1						0	4	5	6	2	1	1	2	0		kp	pj	pj	school of fish jumping			
Site 5	9/14/2020	9:10am	Water Quality Monitoring Equip. Malfunction,		iity, pH and DO	ent in for repair		Monitoring Equip. Malfunction,		iity, pH and DO	ent in for repair	Water Quality Monitoring Equip. Malfunction,		iity, pH and DO	ent in for repair		22.6		1	1						0	1	5	6	3	8	2	3	2		kp	pj	pj				
Site 5	9/21/2020	9:40am	19.51	19.61	19.67	27.26	27.27	27.32				7.81	7.83	7.87	1.8m	9.38	14.3		2	<1						0	4	5	6	0	2	2	1	3		kp	pj	pj				
Site 5	9/28/2020	11:33am	close to rocks	close to rocks	close to rocks	close to rocks	close to rocks	close to rocks	close to rocks	close to rocks	close to rocks	close to rocks	close to rocks	close to rocks	close to rocks	close to rocks	close to rocks		2	<1						1	2	5	6	4	4	1	2	1		es	PJ	PJ	anchor not holding			
Site 5	10/5/2020	8:58 am	19.57	19.51	19.18	27.23	27.24	27.30	broken			8.00	7.94	7.94	1.9	5.28	15.9		1	<1						0	4	5	6	4	2	1	3	2		kp	PJ	PJ				
Site 5																																	

Friends of the Bay 2020 Water Quality Data - Site 6, Seawanhaka Yacht Club PSTP outfall

	Date	Time	H20 Temp TOP (0.5m)	H20 Temp 1.0 m	H20 Temp 0.5 m from BTM	Salinity TOP	Salinity 1.0 m	Salinity BTM	PH Top	PH 1.0 m	Ph .5 m from BTM	Top DO	DO 1.0 m	BTM DO	Secchi	Floor Depth (meters)	Air Temp °C	H2O Temp BTM monthly	Fecal Coliform	Entero	Ammo	Nitrate	Nitrite	Organ	Total	Rainfall in 24	Tidal Stage	Water Color	Surface	Cloud Cover	Wind DIREC	Wind SPEE	Weather	Wave Height		Data Entere	Captain	Sampling	Notes
Site 6	7/13/2020	11:16am	OT WORKING				T OF HEALTH								1.6		27.3		5	<1						1	2	5	6	1	2	1	1	0		kp	pj	pj	
Site 6	7/20/2020	9:22AM	24.55	24.45	23.30	25.68	25.50	25.71	7.79	7.75	7.68	5.60	5.44	4.96	1.2m	6.37	30.8		2	<1						0	4	5	6	2	6	1	2	0		LD	PJ	PJ	
Site 6	7/27/2020	10:52AM	25.28	25.25	24.57	26.32	26.37	26.47	7.87	7.87	7.79	7.04	6.95	6.59	0.9m	5.08	31.2		<1	<1						0	2	5	6	1	7	1	2	0		LD	PJ	PJ	
Site 6	8/3/2020	9:30AM	24.31	24.07	23.08	25.86	25.97	26.13	7.61	7.59	7.48	5.54	4.51	3.90	1.6m	6.78	29.8		1	<1						0	4	5	6	1	7	1	2	1		LD	PJ	PJ	
Site 6	8/10/2020	19:26AM	24.36	24.31	24.15	26.47	26.71	26.69	7.68	7.67	7.65	6.67	6.54	6.55	1.5m	5.78	30.5		5	1						0	2	5	6	0	5	1	1	0		LD	PJ	PJ	
Site 6	8/17/2020	9:15am	23.12	23.05	22.54	26.76	26.70	26.85	7.58	7.58	7.52	4.77	4.64	4.38	1.9m	9.33	21.3		3	7						2	4	5	6	1	8	1	1	1		kp	pj	pj	
Site 6	8/24/2020	10:40am	25.61	25.23	24.80	27.13	27.02	27.06	7.67	7.66	7.62	7.18	6.96	6.81	1.5m	4.87	32.1		1	<1						0	4	5	6	1	8	1	2	0		kp	pj	pj	
Site 6	8/31/2020	9:42am	24.25	24.25	24.23	26.98	26.98	27.00	g used backup		have pH sensor				1.4m	7.13	21.6		1	7						1	4	5	6	4	2	1	3	0		kp	pj	pj	
Site 6	9/8/2020	10:12am	24.25	24.23	24.11	27.17	27.18	27.25	g used backup		have pH sensor				1.8m	5.55	27.7		<1	<1						0	4	5	6	2	6	1	2	0		kp	pj	pj	
Site 6	9/14/2020	9:06am	Water Quality Monitoring Equip. Malfunction,			ity, pH and DO	ent in for repair		Monitoring Equip. Malfunction,		ity, pH and DO	ent in for repair			Water Quality Monitoring Equip. Malfunction,		22.4		1	3						0	1	5	6	3	8	2	3	2		kp	pj	pj	
Site 6	9/21/2020	9:26am	19.73	19.71	19.64	27.32	27.30	27.37				7.60	7.49	7.41	1.7m	5.35	14.9		<1	<1						0	4	5	6	0	2	1	1	1		kp	pj	pj	
Site 6	9/28/2020	11;17am	20.69	20.70	20.62	27.37	27.34	27.38	ade malfunction		ade malfunction		ade malfunction		2.5	7.19	25.3		4	<1						1	2	5	6	4	4	2	3	1		es	PJ	PJ	
Site 6	10/5/2020	8:40 am	19.65	19.67	19.58	27.17	27.17	27.20			broken	7.97	7.91	8.01	2.1	5.32	14.9		<1	<1						0	4	5	6	4	3	1	3	1		kp	PJ	PJ	
Site 6																																			

| | Friends of the Bay 2020 Water Quality Data - **Site 7, Oyster Bay Cove** | | |

Friends of the Bay 2020 Water Quality Data - **Site 8, Oyster Bay STP at White's Creek**

	Date	Time	H20 Temp TOP (0.5m)	H20 Temp 1.0 m	H20 Temp 0.5 m from BTM	Salinity TOP	Salinity 1.0 m	Salinity BTM	PH Top	PH 1.0 m	Ph .5 m from BTM	Top DO	DO 1 m	BTM DO	Secchi (meters)	Floor Depth (meters)	Air Temp (°C)	H2O Temp BTM	Fecal Coliform	Enterococci	Ammonia (NH3)	Nitrate (NO3)	Nitrite (NO2)	Organic Nitrogen	Total Nitrogen	Kjeldahl in 24 hours	Tidal Stage	Water Color	Surface Cowlls	Cloud Cover	Wind DIREC TION	Wind SPEED	Weather	Wave Height	Data Entered by	Capitan	Sampling Leader
Site 8	7/13/2020	10:38AM	OT WORKING				T OF HEALTH								1.2m		35.3		27	<1						1	2	5	6	1	7	0	1	0	LD	PJ	PJ
Site 8	7/20/2020	12:05AM	26.53	25.14	24.52	25.55	25.56	25.57	7.85	7.85	7.65	6.20	5.68	4.88	1.2m	3.75	31.1		2	<1						0	4	5	6	1	8	1	2	0	LD	PJ	PJ
Site 8	7/27/2020	10:25AM	25.45	25.14	25.03	26.14	26.22	26.27	7.77	7.75	7.73	6.44	6.29	6.20	1.0m	1.80	31.5		8	4						0	2	5	6	1	7	2	2	0	LD	PJ	PJ
Site 8	8/3/2020	11:14AM	25.22	25.46	24.34	25.85	25.80	25.90	7.70	7.73	7.53	5.73	5.29	4.49	1.8m	4.37	31.7		4	1						0	4	5	6	1	7	1	1	1	LD	PJ	PJ
Site 8	8/10/2020	10:10AM	24.45	24.19	23.92	26.57	26.56	26.60	7.65	7.61	7.51	6.07	5.72	5.69	1.6m	2.38	29.7		8	<1						0	2	5	6	0	8	1	1	0	LD	PJ	PJ
Site 8	8/17/2020	8:37am	23.59	23.60	23.55	26.37	26.30	26.35	7.60	7.60	7.59	5.36	5.40	5.57	1.5m	3.78	20.1		8	7						2	4	5	6	1	8	1	1	1	kp	pj	pj
Site 8	8/24/2020	10:19AM	25.26	24.98	25.01	26.91	26.99	26.98	7.69	7.63	7.64	7.30	7.19	7.12	1.3m	1.87	31.5		4	<1						0	3	5	6	1	8	1	2	0	KP	PJ	PJ
Site 8	8/31/2020	9:09am	24.17	24.18	24.22	26.78	26.82	26.81	s used backup	save pH sensor		6.53	6.52	6.52	1.4m	3.58	22..7		6	8						1	4	5	6	4	2	1	3	1	KP	PJ	PJ
Site 8	9/8/2020	9:52am	24.02	24.00	23.86	26.93	26.91	26.93	s used backup	save pH sensor		5.93	5.99	6.10	1.6m	2.28	24.1		<1	<1						0	3	5	6	4	7	1	3	0	kp	pj	pj
Site 8	9/14/2020	8:51am	Monitoring Equip. Malfunction,		ity, pH and DO	ent in for repair	Monitoring Equip. Malfunction,		ity, pH and DO	ent in for repair	Water Quality Monitoring Equip. Malfunction,			ity, pH and DO	ent in for repair		22.0		5	<1						0	1	5	6	3	8	2	3	2	kp	pj	pj
Site 8	9/21/2020	9:04AM	19.13	a for this depth		19.15	27.16	a for this depth		27.15	see note page			7.91	a for this depth		7.94	1.6m	2.0	14.5	1	1				0	2	5	6	0	2	2	1	3	KP	PJ	PJ
Site 8	9/28/2020	10:38am	20.55	20.43	20.44	27.10	27.16	27.21	OT WORKING	OT WORKING	OT WORKING	9.11	8.97	8.67	2.1	4.09	22.7		18	2						1	2	5	6	4	4	1	3	1	es	PJ	PJ
Site 8	10/5/2020	10:27am	19.36	19.36	19.36	27.05	27.04	27.08		broken		8.17	8.20	8.24	1.8	2.66	16.1		1	<1						0	4	5	6	4	2	1	3	1	kp	PJ	PJ
Site 8																																			

	Friends of the Bay **2020** Water Quality Data - **Site 9, Roosevelt Beach**																																						
	Date	Time	H20 Temp TOP (0.5m)	H20 Temp 1.0 m	H20 Temp 0.5 m from BTM	Salinity TOP	Salinity 1.0 m	Salinity BTM	PH Top	PH 1.0 m	Ph .5 m from BTM	Top DO	DO 1.0 m	BTM DO	Secchi (m)	Depth (meters)	Air Temp	H20 Temp BTM	Fecal Coliform Bact	Enterococci	Ammonia (NH3)	Nitrate (NO3)	Nitrite (NO2)	Organic Nitrogen	Total Nitrogen	Rainfall in 24 hours	Tidal Stage	Water Color	Surface Condition	Cloud Cover	Wind DIRECTION	Wind SPEED	Weather	Wave Height		Data Entered by	Captain	Sampling Leader
Site 9	7/13/2020	10:22am	OT WORKING				PT OF HEALTH								1.9m		27		6	1						1	2	5	6	1	7	0	1	0		LD	PJ	PJ
Site 9	7/20/2020	9:02AM	24.67	24.49	24.38	25.71	25.69	25.73	7.68	7.66	7.65	5.12	5.08	5.08	1.1m	2.71	32.2		6	<1						0	4	5	6	2	7	1	2	0		LD	PJ	PJ
Site 9	7/27/2020	10:14AM	25.38	25.34	25.38	26.11	26.18	26.02	7.76	7.75	7.75	6.39	6.38	6.35	0.9m	2.10	30.9		3	<1						0	2	5	6	1	6	1	2	0		LD	PJ	PJ
Site 9	8/3/2020	9:09AM	24.67	24.27	23.98	25.80	25.82	25.98	7.60	7.58	7.51	4.92	4.56	4.14	1.3m	3.06	27.9		8	2						0	2	5	6	1	7	1	1	1		LD	PJ	PJ
Site 9	8/10/2020	9:42AM	24.37	24.35	24.35	26.50	26.58	26.51	7.53	7.53	7.52	5.53	5.53	5.57	1.9m	2.22	32.4		3	3						0	2	5	6	0	0	0	1	0		LD	PJ	PJ
Site 9	8/17/2020	08:24am	23.53	23.58	23.53	26.31	26.37	26.68	7.59	7.58	7.56	5.17	4.97	7.98	1.3m	3.41	21.6		24	15						2	4	5	6	1	8	1	1	1		kp	PJ	PJ
Site 9	8/24/2020	10:08AM	25.30	pth too shallow		25.17	26.88	pth too shallow	26.84	7.62	pth too shallow	7.59	6.90	pth too shallow		6.85	1.6m	1.66	29.5		7	<1					0	3	5	6	1	8	1	2	0		KP	PJ	PJ
Site 9	8/31/2020	8:50am	24.23	24.35	24.35	26.77	26.87	26.87	g used backup		have pH sensor		6.04	6.00	6.02	1.2m	3.06	20.2		33	2					1	4	5	6	4	3	1	3	1		KP	PJ	PJ
Site 9	9/8/2020	9:41am	24.03	24.03	24.03	27.01	26.98	26.99	g used backup		have pH sensor		5.56	5.74	5.86	1.7m	2.10	24.3		4	<1					0	3	5	6	4	5	1	3	0		kp	PJ	PJ
Site 9	9/14/2020	8:45am	Monitoring Equip. Malfunction,		ity, pH and DO	ent in for repair	Monitoring Equip. Malfunction,		ity, pH and DO	ent in for repair	Water Quality Monitoring Equip. Malfunction,			ity, pH and DO	ent in for repair		22.7		3	1					0	1	5	6	3	8	2	3	2		kp	PJ	PJ
Site 9	9/21/2020	8:35AM	19.05	a for this depth		19.05	27.14	a for this depth	27.12	see note page			7.98	a for this depth		8.02	na	1.84	13.4		8	3					0	2	5	6	0	2	2	1	2		KP	PJ	PJ
Site 9	9/28/2020	10:27am	20.58	20.54	20.44	27.17	27.20	27.25	see note page				9.97	8.80	8.67	2.35	3.99	23.4		25	2					1	2	5	6	4	4	1	3	1		es	PJ	PJ
Site 9	10/5/2020	8:23 am	19.43	low tide	19.48	26.97	low tide	27.0	broken				7.77	too low	7.87	1.8 at bottom	1.84	15.6		4	1					0	4	5	6	4	2	1	3	1		kp	PJ	PJ
Site 9																																						

	Friends of the Bay **2020** Water Quality Data - **Site 10, Beekman Beach**																																				
	Date	Time	H20 Temp TOP (0.5m)	H20 Temp 1.0 m	H20 Temp 0.5 m from BTM	Salinity TOP	Salinity 1.0 m	Salinity BTM	PH Top	PH 1.0 m	Ph .5 m from BTM	Top DO	DO 1.0 m	BTM DO	Secchi	Floor Depth (meters)	Air Temp	H2O Temp BTM monthly AVG	Fecal Coliform Bacteria	Enterococci	Ammonia (NH3)	Nitrate (NO3)	Nitrite (NO2)	Organic Nitrogen	Total Nitrogen	Rainfall in 24 hours	Tidal Stage	Water Color	Surface Condition	Cloud Cover	Wind DIRECTON	Wind SPEED	Weather	Wave Height		Data Entered by	Captain	Sampling Leader
Site 10	7/13/2020	10:10am	IOT WORKING				PT OF HEALTH								1.6m		35.2		23	1						1	2	5	6	1	7	1	1	1		LD	PJ	PJ
Site 10	7/20/2020	8:48AM	25.63	25.57	24.79	25.24	25.35	25.42	7.78	7.75	7.59	5.73	5.45	4.85	1.0m	5.04	32.2		15	2						0	4	5	6	2	7	0	2	0		LD	PJ	PJ
Site 10	7/27/2020	9:55AM	25.67	25.27	25.08	25.39	26.01	26.16	7.76	7.78	7.70	6.31	6.22	6.00	1.4m	4.08	31.8		11	1						0	2	5	6	1	7	1	2	0		LD	PJ	PJ
Site 10	8/3/2020	8:48AM	25.73	25.84	25.62	25.03	25.29	26.70	7.71	7.71	7.63	6.06	5.80	5.45	1.3m	4.75	28.0		120	13						0	4	5	6	1	7	1	1	0		LD	PJ	PJ
Site 10	8/10/2020	9:24AM	24.47	24.48	24.15	26.38	26.47	26.44	7.60	7.62	7.48	5.77	5.52	5.28	1.4m	4.18	30.4		25	1						0	2	5	6	0	0	1	1	0		LD	PJ	PJ
Site 10	8/17/2020	08:11am	23.67	24.07	23.97	25.52	26.11	26.31	7.62	7.61	7.58	5.61	5.47	5.58	1.2m	5.14	20.3		170	71						2	4	5	4	1	8	1	1	1		kp	PJ	PJ
Site 10	8/24/2020	9:54am	25.11	24.99	24.78	26.52	26.82	26.82	7.61	7.64	7.56	6.91	6.75	6.60	1.4m	3.73	27.4		36	17						0	2	5	6	1	8	1	2	1		kp	PJ	PJ
Site 10	8/31/2020	8:32am	24.1	24.56	24.53	26.61	26.74	26.77	g used backup		have pH sensor	6.37	6.29	6.36	1.2m	5.00	20.9		18	11						1	4	5	6	4	2	1	3	0		kp	PJ	PJ
Site 10	9/8/2020	9:29am	24.15	24.13	24.10	26.77	26.82	26.98	g used backup		have pH sensor	6.03	5.87	5.90	1.5m	4.22	27.1		6	<1						0	2	5	6	3	5	1	3	0		kp	PJ	PJ
Site 10	9/14/2020	8:38am	Monitoring Equip. Malfunction,		iity, pH and DO	ent in for repair	Monitoring Equip. Malfunction,		iity, pH and DO	ent in for repair	Water Quality Monitoring Equip. Malfunction,			iity, pH and DO	ent in for repair		22.0		5	1						0	1	5	6	3	8	2	3	2		kp	PJ	PJ
Site 10	9/21/2020	8:22AM	18.37	18.68	19.00	26.13	26.88	27.08	g used backup		have pH sensor	7.97	7.90	7.91	1.3m	3.94	13.5		54	28						0	2	5	6	0	2	1	1	1		KP	PJ	PJ
Site 10	9/28/2020	10:12 am	20.53	20.48	20.35	26.77	27.08	27.15	sonde not working			8.8	8.67	8.56	2.1	5.9	23.1		39	2						1	2	5	6	4	4	1	3	1		es	PJ	PJ
Site 10	10/5/2020	8:11am	19.3	19.27	19.33	26.65	26.80	26.88	broken			7.68	7.78	7.93	1.80	3.95	14.80		93	26						0	3	5	3	4	2	1	3	1		kp	PJ	PJ
Site 10																																					
Site 10																																					
Site 10																																					
Site 10																																					
Site 10																																					
Site 10																																					
Site 10																																					
Site 10																																					
Site 10																																					
Site 10																																					
Site 10																																					
Site 10																																					
Site 10																																					
Site 10																																					
Site 10																																					
Site 10																																					
Site 10																																					

	Friends of the Bay **2020** Water Quality Data - Site 11, West Harbor																																						
	Date	Time	H20 Temp TOP (0.5m)	H20 Temp 1.0 m	H20 Temp 0.5 m from BTM	Salinity TOP	Salinity 1.0 m	Salinity BTM	PH Top	PH 1.0 m	Ph .5 m from BTM	Top DO	DO 1.0 m	BTM DO	Secchi (m)	Floor Depth (meters)	Air Temp	H2O Temp BTM monthly	Fecal	Enterococ	Ammonia	Nitrate	Nitrite	Organic	Total Nitro	Rainfall in	Tidal Stag	Water	Surface	Cloud	Wind DIRE	Wind SPE	Weather	Wave		Data Enter	Captain	Sampling Leader
Site 11	7/13/2020	9:35am	26.01	25.84	23.09	25.41	25.46	25.92	7.89	7.88	7.59	6.87	6.45	5.46	1.5m	2.62	28.6	g problems with motor								1	2	5	6	1	7	1	1	1		LD	PJ	PJ
Site 11	7/20/2020	8:31AM	26.13	25.84	25.35	25.22	25.36	25.50	7.76	7.74	7.66	6.01	5.94	5.65	1.0m	2.55	332.6		2	<1						0	4	5	6	2		0	2	0		LD	PJ	PJ
Site 11	7/27/2020	9:15AM	26.68	26.75	25.37	26.01	26.02	26.18	7.97	7.96	7.72	7.87	7.33	6.36	0.8m	2.91	30.5		1	<1						0	2	5	6	1	6	1	2	0		LD	PJ	PJ
Site 11	8/3/2020	8:12AM	25.95	25.91	25.55	25.36	25.52	25.65	7.58	7.56	7.51	5.13	4.89	4.68	1.2m	3.18	27.3		<1	1						0	4	5	6	3	7	1	2	1		LD	PJ	PJ
Site 11	8/10/2020	8:57AM	25.37	25.35	25.20	26.20	26.20	26.33	7.61	7.61	7.60	5.88	5.86	5.87	1.1m	3.69	28.7		4	<1						0	2	5	6	0	5	1	1	0		LD	PJ	PJ
Site 11	8/17/2020	07:36am	24.03	24.05	24.04	26.27	26.33	26.23	7.58	7.57	7.56	5.48	5.45	5.46	1.4m	4.24	19.8		2	<1						2	4	5	6	1	8	1	1	1		kp	PJ	PJ
Site 11	8/24/2020	9:12am	25.67	25.42	25.23	26.83	26.85	26.89	7.76	7.72	7.65	7.35	7.16	7.01	1.0m	2.48	29.6		1	2						0	2	5	6	1	0	0	2	0		kp	PJ	PJ
Site 11	8/31/2020	7:55am	24.48	24.47	24.44	26.72	26.73	26.73	g used backup	have pH sensor		6.48	6.50	6.59	1.0m	3.44	19.1		1	<1						1	3	5	6	4	2	1	3	0		kp	PJ	PJ
Site 11	9/8/2020	8:49am	24.31	24.29	24.26	26.71	26.73	26.82	g used backup	have pH sensor		6.21	6.12	6.14	1.1m	2.87	25.1		3	<1						0	2	5	6	3	0	0	2	0		kp	PJ	PJ
Site 11	9/14/2020	8:22am	Monitoring Equip. Malfunction,		hity, pH and DO	ent in for repair	Monitoring Equip. Malfunction,		hity, pH and DO	ent in for repair	Water Quality Monitoring Equip. Malfunction,			hity, pH and DO	ent in for repair		21.7		4	<1						0	4	5	6	3	8	2	3	2		kp	PJ	PJ
Site 11	9/21/2020	7:38AM	17.57	17.58	17.58	26.96	26.98	26.99	g used backup	have pH sensor		8.23	8.23	8.27	1.0m	2.82	13.2		<1	<1						0	2	5	6	0	2	3	1	3		KP	PJ	PJ
Site 11	9/28/2020	9:47am	20.44	20.44	20.40	27.15	27.14	27.11	sonde broken	sonde broken	sonde broken	8.93	8.80	8.70	2.2	4.57	22.9		5	3						1	4	5	6	4	4	2	3	1		es	PJ	PJ
Site 11	10/5/2020	7:44 am	18.58	18.58	18.58	26.97	26.98	27.0	broken			7.54	7.64	7.79	1.6	2.9	14.1		<1	<1						0	3	5	6	4	2	1	3	1		kp	PJ	PJ
Site 11																																						

Friends of the Bay **2020** Water Quality Data - **Site 12, Turtle Cove**

	Date	Time	H20 Temp TOP (0.5m)	H20 Temp 1.0 m	H20 Temp 0.5 m from BTM	Salinity TOP	Salinity 1.0 m	Salinity BTM	PH Top	PH 1.0 m	Ph .5 m from BTM	Top DO	DO 1 m	BTM DO	Secchi (m)	Floor Depth (meters)	Air Temp	H2O Temp BTM monthly AVG	Fecal Coliform Bacteria	Enterococci	Ammonia (NH3)	Nitrate (NO3)	Nitrite (NO2)	Organic Nitrogen (N)	Total Nitrogen	Total Nitrogen	Rainfall in 24 hours	Tidal Stage	Water Color	Surface Condition	Cloud Cover	Wind DIRECTION	Wind SPEED	Weather	Wave Height		Data Entered by	Captain	Sampling Leader	Notes
Site 12	7/13/2020	9:46am	IOT WORKING	AMPLE COLLECTED FOR DEPT OF HEALTH											1.3m		26.5		<1	<1							1	2	5	6	1	7	1	1	1		LD	PJ	PJ	
Site 12	7/20/2020	11:37AM	28.32	27.94	25.54	25.44	25.36	25.53	7.87	7.97	7.63	6.26	5.85	4.84	0.9m	3.71	32.4		2	<1							0	1	5	6	2	1	1	2	0		LD	PJ	PJ	
Site 12	7/27/2020	9:32AM	27.27	27.26	25.51	25.94	26.01	26.01	7.64	7.63	7.46	4.79	4.11	4.26	0.9m	2.00	30.5		1	<1							0	2	5	6	1	6	1	2	0		LD	PJ	PJ	
Site 12	8/3/2020	8:23AM	26.64	26.64	26.64	25.45	25.54	25.51	7.57	7.57	7.57	5.31	5.32	5.37	1.1m	2.06	27.4		15	8							0	4	5	6	3	8	1	2	1		LD	PJ	PJ	
Site 12	8/10/2020	9:08AM	26.32	26.20	26.94	26.33	26.34	26.29	7.69	7.67	7.58	5.74	5.50	5.12	1.2m	1.97	27.6		<1	<1							0	2	5	4	0	7	1	1	0		LD	PJ	PJ	
Site 12	8/17/2020	7:56am	23.83	23.83	23.80	26.24	26.33	26.46	7.60	7.60	7.59	5.44	5.45	5.56	1.5m	3.07	19.9		11	<1							2	4	5	6	1	8	1	1	1		kp	PJ	PJ	
Site 12	8/24/2020	9:33am	26.45	pth too shallow		26.37	26.80	pth too shallow		26.86	7.62	pth too shallow		7.61	6.14	pth too shallow		6.25	0.5m	1.64	27.8		4	<1				0	2	5	6	1	4	1	2	0		kp	PJ	PJ	
Site 12	8/31/2020	8:10am	24.01	24.04	23.45	26.67	26.69	26.77	g used backup		have pH sensor		5.84	5.74	6.10	0.7m	2.83	20.3		2	1							1	4	5	6	4	1	1	3	0		kp	PJ	PJ	
Site 12	9/8/2020	9:03am	24.20	24.13	24.12	26.59	26.58	26.59	g used backup		have pH sensor		6.28	6.27	6.38	0.7m	2.10	24.3		2	<1							0	2	5	6	4	0	0	3	0		kp	PJ	PJ	Seagulls feeding on fish school
Site 12	9/14/2020	8:28am	Monitoring Equip. Malfunction,		iity, pH and DO	ent in for repair		Monitoring Equip. Malfunction,		iity, pH and DO	ent in for repair		Water Quality Monitoring Equip. Malfunction,		iity, pH and DO	ent in for repair		21.9		1	<1							0	4	5	6	3	8	2	3	2		kp	PJ	PJ	
Site 12	9/21/2020	8:01AM	17.20	17.20	17.21	26.97	26.99	26.98	g used backup		have pH sensor		8.03	8.04	8.10	1.3m	1.97	12.7		2	2							0	2	5	6	0	2	2	1	2		KP	PJ	PJ	
Site 12	9/28/2020	9:57am	20.87	20.87	20.85	26.89	26.88	26.87	sonde broken				7.53	7.53	7.55	1.2	3.81	22.5		18	4							1	4	5	6	4	4	2	3	1		es	PJ	PJ	
Site 12	10/5/2020	7:58 am	17.91	low tide	17.85	26.69	low tide	26.79	broken				7.10	low tide	7.54	1.6	1.78	14.2		3	1							0	3	5	6	4	2	1	3	1		kp	PJ	PJ	
Site 12																																							
Site 12																																							
Site 12																																							
Site 12																																							
Site 12																																							
Site 12																																							
Site 12																																							
Site 12																																							
Site 12																																							
Site 12																																							
Site 12																																							
Site 12																																							
Site 12																																							
Site 12																																							
Site 12																																							
Site 12																																							
Site 12																																							
Site 12																																							

| | Friends of the Bay **2020**Water Quality Data - **Site 13, Mill Neck Creek East** | | |

| | Friends of the Bay **2020** Water Quality Data - **Site 14, Mill Neck Creek West** | | |

| | Friends of the Bay 2020 Water Quality Data - Site 15, Mill Neck Creek South | | |

	Friends of the Bay 2020 Water Quality Data - Site 16, Mill Neck Creek North																																								
	Date	Time	H20 Temp TOP (0.5m)	H20 Temp 1.0 m	H20 Temp 0.5 m from BTM	Salinity TOP	Salinity 1.0 m	Salinity BTM	PH Top	PH 1.0 m	Ph .5 m from BTM	Top DO	DO 1.0	BTM DO	Secchi (m)	Floor Depth (meters)	Air Temp	H2O Temp BTM monthly AVG	Fecal Coliform Bacteria	Enterococci	Ammonia (NH3)	Nitrate (NO3)	Nitrite (NO2)	Organic Nitrogen (N)	Total Nitrogen	Rainfall in 24 hours	Tidal Stage	Water Color	Surface Condition	Cloud Cover	Wind DIRECTON	Wind SPEED	Weather	Wave Height		Data Entered by	Captain	Sampling Leader
Site 16	7/13/2020	A AMPHIBIAN NOT WORKING		WATER SAMPLE COLLECTED FOR DEPT OF HEALTH												NO SPECIMEN COLLECTED MOTOR PROBLEM																				LD	PJ	PJ
Site 16	7/20/2020		TIDE TOO LOW																							0	1	5								LD	PJ	PJ
Site 16	7/27/2020	8:10AM	26.56	OO SHALLOW	26.47	25.52	OO SHALLOW	25.75	7.49	OO SHALLOW	7.56	5.08	OO SHALLOW	5.30	0.7m	1.36	30.1	D DUE TO EXTREME HEAT	100+ DEGREES						0	2	5	6	2	6	1	2	0		LD	PJ	PJ
Site 16	8/3/2020	12:13PM	27.57	26.44	26.15	25.23	25.51	25.58	7.61	7.61	7.60	5.67	5.45	5.48	0.9m	2.33	30.4		36	<1						0	1	5	6	0	8	1	1	0		LD	PJ	PJ
Site 16	8/10/2020		TIDE TOO LOW				TIDE TOO LOW																			0	3									LD	PJ	PJ
Site 16	8/17/2020	11:41AM	23.86	23.96	23.93	25.50	26.01	26.20	7.53	7.59	7.58	5.56	5.66	5.67	0.8m	2.15	23.5		260	7						2	2	5	6	1	8	1	1	1		kp	pj	pj
Site 16	8/24/2020	DO SHALLOW	at depth finder reading on boat		DEPTH TOO SHALLOW						DEPTH TOO SHALLOW					DEPTH TOO SHALLOW																			KP	PJ	PJ
Site 16	8/31/2020		n/a	NOUGH TIME) LIMITATIONS																																KP	PJ	PJ
Site 16	9/8/2020	pth too shallow	data or sample		tide too low /depth too shallow		data or sample			tide too low /depth too shallow		data or sample		tide too low /depth too shallow		data or sample			tide too low /depth too shallow		data or sample		tide too low /depth too shallow		data or sample			tide too low /depth too shallow		data or sample			kp	pj	pj
Site 16	9/14/2020	8:02am	Monitoring Equip. Malfunction,	ity, pH and DO	ent in for repair		Monitoring Equip. Malfunction,		ity, pH and DO	ent in for repair	Water Quality Monitoring Equip. Malfunction,		ity, pH and DO	ent in for repair			21.6		7	7						0	4	5	6	3	8	2	3	2		kp	pj	pj
Site 16	9/21/2020	pth too shallow		tide too low /depth too shallow					tide too low /depth too shallow					tide too low /depth too shallow					tide too low /depth too shallow					tide too low /depth too shallow											KP	PJ	PJ
Site 16	9/28/2020	9.09 am	21.03	20.98	20.89	26.41	26.52	26.64		sonde broken		7.65	7.66	7.63	1.2	2.4	21.8		61	5						1	4	5	6	4	4	1	3	1		es	PJ	PJ
Site 16																																							
Site 16																																							
Site 16																																							
Site 16																																							
Site 16																																							
Site 16																																							
Site 16																																							
Site 16																																							
Site 16																																							
Site 16																																							
Site 16																																							
Site 16																																							
Site 16																																							
Site 16																																							
Site 16																																							
Site 16																																							
Site 16																																							
Site 16																																							
Site 16																																							
Site 16																																							

| | Friends of the Bay **2020** Water Quality Data - Site 17, The Birches STP | | |

	Friends of the Bay **2020** Water Quality Data - Site 18, Mill Neck Cove																																		
	Date	Time	H20 Temp TOP (0.5m)	H20 Temp 1.0 m	H20 Temp 0.5 m from BTM	Salinity TOP	Salinity 1.0 m	Salinity BTM	PH Top	PH 1.0 m	Ph .5 m from BTM	Top DO	DO 1.0	BTM DO	Secchi (m)	Floor Depth (meters)	Air Temp	H2O Temp BTM monthly AVG	Fecal Coliform Bacteria	Enterococci	Amm	Nitrate	Nitrite	Organic	Total Nit	Rainfall in 24 hours	Tidal Stage	Water Color	Surface Condition	Cloud Cover	Wind DIRECTON	Wind SPEED	Weather	Wave Height		Data Entered by	Captain	Sampling Leader	Notes
Site 18	7/13/2020	A AMPHIBIAN NOT WORKING		WATER SAMPLE COLLECTED FOR DEPT OF HEALTH												NO SPECIMEN COLLECTED MOTOR PROBLEM																				LD	PJ	PJ	
Site 18	7/20/2020	TIDE TOO LOW																									1	5		2		1	2	0		LD	PJ	PJ	
Site 18	7/27/2020	9:02AM	26.15	26.13	26.08	25.95	25.99	25.04	7.68	7.71	7.73	6.34	6.37	6.37	0.9m	1.77	31.6	EXTREME HEAT 100+ DEGREES							0	2	5	6	2	5	1	2	0		LD	PJ	PJ	
Site 18	8/3/2020	12:44PM	26.45	26.41	25.77	25.60	25.55	25.57	7.70	7.70	7.59	5.82	5.65	5.13	1.1m	3.09	31.6		2	<1					0	1	5	6	0	8	1	1	1		LD	PJ	PJ	
Site 18	8/10/2020	8:32AM	25.44	N/A	25.39	26.21	N/A	26.20	7.59	N/A	7.57	5.78	N/A	5.81	1.3m	1.63	28.6		3	1					0	2	5	6	0	6	1	1	0		LD	PJ	PJ	
Site 18	8/17/2020	12:06pm	24.72	24.52	24.05	26.15	26.15	26.37	7.60	7.66	7.60	6.05	5.88	5.96	1.2m	2.91	25.3		12	1					2	2	5	6	0	8	1	1	1		kp	pj	pj	
Site 18	8/24/220	8:54AM	25.61	OO SHALLOW	25.42	26.30	OO SHALLOW	26.54	7.38	OO SHALLOW	7.46	5.26	OO SHALLOW	5.70	0.7M	1.49	31.9								0	2	5	6	1	4	1	2	0		KP	PJ	PJ	
Site 18	8/31/2020	12:11PM	24.45	24.43	24.36	26.82	26.85	26.91	g used backup	have pH sensor		6.80	6.66	6.72	1.1m	3.25	26.4		8	<1					1	4	5	6	4	2	1	3	1		kp	pj	pj	
Site 18	9/8/2020	8:28am	24.16	other readings		26.55	other readings	was not working	used backup	have pH sensor		6.06	other readings		1.1m	1.62	24.3		2	<1					0	2	5	6	2	5	1	2	0		kp	pj	pj	
Site 18	9/14/2020	7:38am	Monitoring Equip. Malfunction,		ity, pH and DO	ent in for repair	Monitoring Equip. Malfunction,		ity, pH and DO	ent in for repair	Water Quality Monitoring Equip. Malfunction,			ity, pH and DO	ent in for repair		21.3		23	9					0	4	5	6	3	8	2	3	2		kp	pj	pj	
Site 18	9/21/2020	11:35AM	17.34	17.34	17.37	26.62	26.64	26.64	g used backup	have pH sensor		8.54	8.54	8.54	1.4m	2.10	15.9		33	4					0	4	5	6	0	2	2	1	1		KP	PJ	PJ	
Site 18	9/21/2020	8:13 am	20.75	20.73	20.69	26.70	26.71	26.72				8.08	8.07	8.06	1.7	3.05	21.3		20	3					1	4	5	6	4	5	1	3	1		es	PJ	PJ	
Site 18	9/28/2020	8:13am	20.75	20.73	20.69	26.70	26.71	26.72		ph sensor broken		8.08	8.07	8.06	1.7	3.05	21.3		20	3					1	4	5	6	4	5	1	3	1		es	PJ	PJ	
Site 18																																			

| | Friends of the Bay 2020 Water Quality Data - Site 19, Flowers Oyster Hatchery | | |